

Technical Service Bulletin – Model DB2-B730 NBN

This is a Technical Service Bulletin for Industrial Sewing Machine model DB2-B730 NBN. These machines were produced between September, 1991 and June, 1994. According to our records, there were only 110 of these machines sold in the whole of Europe.

The DB2-B730 NBN machines include a control box under the sewing machine table. Dust can accumulate in the control box and may contribute to a **potentially hazardous condition**.


If you have one of these machines, please contact Brother either at the contact details below, or by using the following E-Mail address: tsb-b730nbn@brother-ism.de

We will then arrange for an inspection, cleaning and, if necessary, repair to the control box electronics, without charge.

This situation applies **only** to the version of the machines which are ...NBN type

Thank you for your cooperation in this matter and please accept our apologies for any inconvenience caused. Please be advised that Brother strives to continuously improve the quality of our products so that our customers can rely on us.

For identification of whether your machine is affected, please check if **NBN** is described either on the panel of the sewing machine head, the name plate or the control box under the machine, as mentioned below.



Full contact details:

**Brother Internationale Industriemaschinen GmbH
Düsseldorfer Strasse 7 – 9
46446 Emmerich am Rhein / Germany
Phone: (+49) (0) 28 22 / 6 09 – 0
FAX: (+49) (0) 28 22 / 609 - 50**